

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/15/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S09E_012MH

Test ID: D1032-010007

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S09E_012MH
0			Water Level	
93	02		Tap Factory Active	From 506 Edgewood
93.19999695			Dye Test Visible	@ TFA - toilet
93.19999695			Dye Test Not Visible	@ TFA - FROM AREA UNDER DOWN SP
93.19999695			Manhole	S09C_031MH
93.19999695			End of Survey	DYE TEST COMPLETED